

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Body: S.
Marymount Public School
Kattakudi, Kottayam

Total area - 15504.44 m²
2 nos. Four storied building (Rec)
No. - Three storied building (Rec)
(Including class room, hall, toilet)

5. Period for which the certificate is issued
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner

1st June 2023 to 31st May 2024

All

No

8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

Yes


Sound and in good condition

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 29/05/2023 and found to be fit / unfit to conduct classes, for the period 2023 - 2024 for the reasons stated above.

Place: Ettimanoor
Date: 30/05/2023



(Seal)

Assistant Engineer
SECTION 13
ETTIMANOOR MUNICIPALITY